

Scratch and Dent

ITEM #	Model #	Serial #	Description	SEER	Size	Ref	QTY	Notes
115207	N4A318AKB	E112402226	Split / Air Conditioner	13 SEER	1.5 Ton	R410a	1	Installed (Customer needed a Heat Pump)
115440	NXA660GKA	E122816858	Split / Air Conditioner	16 SEER	5.0 Ton	R410a	1	Freight Damage, Liquid Service Valve needs Replaced. Part included # 1172792
114918	R2H330GKR	X114971437	HP Condenser Dry	13 SEER	2.5 Ton	R22	1	Installed (Customer needed A/C)
101036	PHD560000KTP0C	C111046305	Pkg Heat Pump	14.5 SEER	5.0 Ton	R410a	1	Installed
1000306	PHD336000L000C	C124911529	Pkg Heat Pump	13.5 SEER	3.0 Ton	R410a	1	Wrong Voltage, Installed as side draft. (460v, 3phase)



8/26/2013